

where to insert the glue for the lifting handle

This is a template type diagram which shows where the holes in the main spar need to be drilled to be reinforced by one of the most important AD's ever issued for the Diamant. This AD was published after a fatal accident and is discussed in other papers.

